Search History 09/496, 549

	Туре	Hits	Search Text
1	BRS	5518	"bandwidth allocation"
2	BRS	0	S1 and ("bandwidth management" same extra)
3	BRS	610	S1 and ("bandwidth management")
4	BRS	0	S4 and (legacy near20 preambles)
5	BRS	1	S4 and legacy
6	BRS	7	S3 and (channel same extension)
7	BRS	284395	(switch\$3 same dynamical\$2 samae packet\$1)
8	BRS	268	S7 and ("20 Mhz" and "40 Mhz")
9	BRS	0	S12 and (dynamical\$2 and "packet by packet")
10	BRS	38	S12 and (dynamical\$2 and packet)
11	BRS	25 	S14 and monitor\$3
12	BRS	/ h	S8 and (overlapping or "non- overlapping")
13	BRS	3	S15 and (bandwidth same (first near12 second))
14	BRS	2	"20060002361"

	DBs	Time Stamp	Comments	Error Definition
1	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2006/09/26 12:29		
2	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2006/09/26 12:30		
3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2006/09/26 12:30		
4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2006/09/26 12:31		
5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2006/09/26 12:31	·	,
6	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2006/09/26 12:46		
7	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2006/09/26 12:47		
8	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2006/09/26 13:04		
9	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2006/09/26 13:07		
10	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2006/09/26 13:07		
11	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2006/09/26 13:07		
12	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2006/09/26 12:49		
13	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2006/09/26 13:16		
14	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	2006/09/26 13:57		

	Туре	Hits	Search Text
15	BRS	2	"20040023674"
16	BRS	2	S9 and ("bandwidth management")
17	BRS	7	S9 and (legacy same preambles)
18	BRS	674	(("20 Mhz" and "40 Mhz")same signal\$1)
19	BRS	2	"20050190724"
20	BRS	2	"20050068922"
21	BRS	2	"20060146869"
22	BRS	2	S21 and "non-overlapping"
23	BRS	2 ,	S21 and "wireless device"
24	BRS	2	"20060182017"
25	BRS	4950	(rout\$3 same digital same call)
26	BRS	322	S25 and (external or remote) same (channel same switch)
27	BRS	322	S25 and ((external or remote) same (channel same switch))
28	BRS	61	S27 and (bypass\$3 same switch)

09/496,545

Error Comments DBs Time Stamp Definition US-PGPUB; USPAT; 15 2006/09/26 14:30 USOCR; EPO; JPO; DERWENT; IBM TDB US-PGPUB; USPAT; 16 2006/09/26 12:53 USOCR; EPO; JPO; DERWENT; IBM TDB US-PGPUB; USPAT; 17 USOCR; EPO; JPO; 2006/09/26 12:53 DERWENT; IBM TDB US-PGPUB; USPAT; 18 2006/09/26 13:05 USOCR; EPO; JPO; DERWENT; IBM TDB US-PGPUB; USPAT; 2006/09/26 13:16 19 USOCR; EPO; JPO; DERWENT; IBM_TDB US-PGPUB; USPAT; 2006/09/26 13:18 20 USOCR; EPO; JPO; DERWENT; IBM TDB US-PGPUB; USPAT; 21 2006/09/26 13:57 USOCR; EPO; JPO; DERWENT; IBM TDB US-PGPUB; USPAT; 22 USOCR; EPO; JPO; 2006/09/26 14:00 DERWENT; IBM TDB US-PGPUB; USPAT; 2006/09/26 14:29 23 USOCR; EPO; JPO; DERWENT; IBM TDB US-PGPUB; USPAT; 24 2006/09/26 13:17 USOCR; EPO; JPO; DERWENT; IBM TDB US-PGPUB; USPAT; 25 USOCR; EPO; JPO; 2006/10/30 10:54 DERWENT; IBM_TDB US-PGPUB; USPAT; 26 2006/10/30 10:55 USOCR; EPO; JPO; DERWENT; IBM TDB US-PGPUB; USPAT; 27 2006/10/30 10:55 USOCR; EPO; JPO; DERWENT; IBM_TDB US-PGPUB; USPAT; 28 USOCR; EPO; JPO; 2006/10/30 10:58 DERWENT; IBM TDB